

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,025,448 B2
APPLICATION NO. : 10/665752
DATED : April 11, 2006
INVENTOR(S) : David Olsen


Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 10, lines 47-49, in Claim 5, delete "The method of Claim 1, wherein the step of providing a fluid interconnect tower includes positioning a filter at the distal end of the fluid interconnect tower." and insert -- The method of Claim 1, further comprising: filling the ink container with a supply of liquid pigmented ink. --, therefor.

Signed and Sealed this

Nineteenth Day of May, 2009

A handwritten signature in cursive script that reads "John Doll".

JOHN DOLL
Acting Director of the United States Patent and Trademark Office